Product Information

METALLIC FOIL

Description Metallic Foil allows you to create stunning metallic effects with its thin

composition, good elasticity and scratch resistance.

Usage Information Due to the many different base materials available on the market, the

following instructions are given as a guideline only:

Transfer setup

Temperature: 140-150°C Time: 8-12 seconds

Pressure: medium (3÷4 bar)

Procedure Cut the material

Weed the exceeding material

Remove the design from the backing Remove the application tape warm

Certifications EN 71 and CPSIA through SGS

Suitable textiles Cotton, polyester and blends of these materials

(not suited for treated and dye sublimation fabrics)

Washing Instructions Wait **24h** after the heat transfer

Wash inside out 40°C

Do not use bleach or other aggressive chemical agents.

Dry clean: **no** Tumble dry: **yes**



Tel: 01827 300500 Web: www.grafityp.co.uk E-mail: sales@grafityp.co.uk