

PU

SPECIFICATIONS

Composition	± Average Thickness	Q Carrier			
PU	85 microns	Non adhesive polyester	REACH n° 1907/2006/EU OEKO-TEX ® CONFIDENCE IN TEXTILES STANDARD 100 19CX00041 CENTROCOT		

APPLICATION INSTRUCTIONS

⊘ Applies on	SUGGESTED CUTTING SETTINGS			TRANSFER SETTINGS			
cotton, polyester, poly/cotton blends (not suited for treated	Blade	<u></u> Pressure	» Speed	Time	Temperature	Pressure	Peel
and dye sublimated textiles)	45°	50 gf	30cm/sec	15 seconds	150°C (302°F)	Medium (2,5/3,5 bar)	cold

- → Cut the material mirrored
- → Peel off excess material
- → Place the decoration on the garment
- → Apply following the recommended parameters
- → Remove the carrier when cold

PRODUCT HIGHLIGHTS

- → High resistance to washing
- → Very thin material

$oxed{oldsymbol{ol}}}}}}}}}}}}}}}}}}}$

CARE AND WASHING RECOMMENDATIONS

Washing	Ironing	Tumble dry	Ony cleaning	Storage Shelf Life	Storage Temperature	Storage Conditions	∮ ⊳ Position
Up to 60°C, best inside-out	YES best inside-out	YES (cotton cycle)	NO	Up to 2 years	Between 18°C and 26°C	Away from sunlight and dust	Vertical

- → Wait 24 hours after the application before the first wash
- → Respect the textile recommendations
- ightarrow Do not bleach or use aggressive chemical agents



Tel: 01827 300500 Web: www.grafityp.co.uk E-mail: sales@grafityp.co.uk