



COLORPRINT EASY

SPECIFICATIONS

| Composition | Average Thickness | Carrier | Certifications |
|-------------|-------------------|------------------------|--|
| PU | 90 microns | non adhesive polyester | <p>REACH n° 1907/2006/EU</p> <p>   </p> <p> OEKO-TEX® CONFIDENCE IN TEXTILES STANDARD 100 17CX00043 CENTROCOT </p> |

APPLICATION INSTRUCTIONS

| Applies on | SUGGESTED CUTTING SETTINGS | | | TRANSFER SETTINGS | | | |
|---------------------------------------|----------------------------|----------|-----------|-------------------|---------------|----------------------|------|
| cotton, polyester, poly/cotton blends | Blade | Pressure | Speed | Time | Temperature | Pressure | Peel |
| | 45° | 50 gf | 25 cm/sec | 15 seconds | 155°C (310°F) | Medium (2,5/3,5 bar) | hot |

- Print & cut material
- Allow the print to dry at least 2 hours
- Weed excess material
- Remove the print from the carrier by hand using TTD Easy and place it on the garment
- Heat apply at the conditions shown above
- Peel TTD Easy hot

 **NOTE:** We highly recommend to perform a test before launching a production.

CARE AND WASHING RECOMMENDATIONS

| Washing | Ironing | Tumble dry | Dry cleaning | Storage Shelf Life | Storage Temperature | Storage Conditions | Position |
|------------------------|----------------|--------------------|--------------|--------------------|-----------------------|-----------------------------|----------|
| Up to 40°C, inside-out | YES inside-out | YES (cotton cycle) | NO | Up to 2 years | Between 18°C and 26°C | Away from sunlight and dust | Vertical |

- Wait 24 hours after the application before the first wash
- Respect the textile recommendations
- Do not bleach or use aggressive chemical agents